




P15=P16=P17=P20=P21=P24




P22




S15-S16-S17-S20-S21-S22-S24




P10





P8=P9=P11=P12=P14=P19



S9=S9=S10=S11=S12=S14=S19



P13=P18



RELAÇÃO DO AÇO	
P1	2xP2
2xP7	6xP8
2xP13	6xP15
P23	S1
2xS13	7xS16
2xS25	8xS26